

ECODET 1

DESCRIZIONE

PRELAVAGGIO A SCHIUMA ATTIVA

Detergente schiumogeno ad alta viscosità. Ottimo come prelavaggio assicura una buona detergenza ed una schiuma persistente. Adatto a tutte le superfici verniciate. Indicato per la rimozione di sporchi grassi così come smog traffic film e sporco stradale in genere. Può essere impiegato nel settore dell'autotrazione, dell'industria ed in ambito alimentare per i piani di sanificazione H.A.C.C.P.

- Facilmente risciacquabile
- Delicato sulle superfici

CARATTERISTICHE CHIMICO-FISICHE

PARAMETRI	VALORI
Aspetto fisico	Liquido limpido viscoso, verde
Odore	Eucalipto
pH	13,5 ± 0,5
pH 1%	11,1 ± 0,5

ECODET 1

DESCRIPTION

ACTIVE FOAM PRE-WASH

High viscosity foaming detergent. Excellent as a pre-wash, thorough and complete cleaning with high foaming long lasting action. Suitable for all painted surfaces. Indicated for removing greasy dirt and for smog, traffic film and road dirt in general. May be used in the automotive sector, in industry and in food applications for H.A.C.C.P. sanitising plans.

- Easily rinsable
- Does not corrode the surfaces

PHYSICAL – CHEMICAL PARAMETERS

PARAMETERS	VALUES
Physical aspect	Limpid liquid viscous, green
Odour	Eucalyptus
pH	13,5 ± 0,5
pH 1%	11,1 ± 0,5

APPLICAZIONE E DOSAGGIO

Impiego manuale: Diluire come da tabella. Spruzzare la soluzione con nebulizzatore o pompa proporzionale sulla superficie possibilmente asciutta e risciacquare immediatamente ed abbondantemente con idropulitrice ad acqua fredda o calda.

Tipo sporco	MANUALE	
	Ecodet 1 : Acqua	%
Pesante	1:25 - 1:30	4 - 3
Medio	1:30 - 1:40	3 - 2,5
Leggero	1:40 - 1:50	2,5 - 2

AVVERTENZE

Evitare il contatto con alluminio e le sue leghe. Evitare di operare al sole o su superficie calda. Si consiglia di distribuire la soluzione di prodotto in modo abbondante ed uniforme, partendo dal basso verso l'alto.

CONTIENE TENSIOATTIVI CONFORMI AL
REG. 648/2004/CE

APPLICATION

Manual use: Dilute as in the table. Spray the solution with a nebulizer or proportional pump onto the possibly dry surface and rinse immediately and abundantly with a pressure cleaner with cold or hot water.

Type of dirt	MANUAL	
	Ecodet 1 : Water	%
Heavy	1:25 - 1:30	4 - 3
Medium	1:30 - 1:40	3 - 2,5
Light	1:40 - 1:50	2,5 - 2

WARNINGS

Avoid contact with aluminum and its alloys. Avoid working in the sun or on hot surface. It is advisable to spread the solution of the product in plentiful and uniform way from the bottom upwards.

CONTAINS SURFACTANTS ACCORDING TO
REG. 648/2004/CE